

Statistical process control (SPC)

Goals

- Establishing an intelligent **information** system to describe the **process evolution**, able to:
 - ✓ **Detect abnormal** behaviour as fast as possible.
 - ✓ **Identify** the **source** of the **abnormal** behaviour.
 - ✓ **Correct** the **abnormal** behaviour and **avoid** it in the future.

Process control. The main idea

- Visualize the process evolution from a series of measurements acquired during the process.
- Visualization tools should:
 - ✓ Be statistically sound,
 - ✓ Allow easy and fast detection of presence and source of abnormal behaviour.

Natural variability vs. special variability

Natural variability

Inherent to the process.

- Permanent.
- Produces a stable and predictable behaviour.
- In the presence of natural variability, the process is **UNDER CONTROL.**

Special variability

Fluctuations strange to the process.

- Happens in unusual or specific circumstances.
- Causes an erratic and unpredictable process behaviour.
- In the presence of anomalous variability, the process is **OUT OF CONTROL.**


Natural variability vs. special variability

Natural variability



- Process under statistical control.
- Process working in **normal operating conditions (NOC)**.

Special variability




- Process out of statistical control.
- Does not work in NOC conditions.

Process typology

● Batch processes.


- ✓ Done in a discontinuous way. Limited duration.
- ✓ Several (or many) variables are controlled 'on/in-line' (*process variables*).
- ✓ Few variables related to quality attributes are measured 'off-line' in the final product (*quality variables*).



Process typology

Continuous processes.

- ✓ Take place in a non-stop way.
- ✓ Many process variables are controlled on or in-line.
- ✓ Control of end product is done in real time by prediction of quality attributes based on previously established statistical models among process variables and quality variables.



Tools for process control

• Univariate SPC tools.

- ✓ Control charts based on a process or a quality variable.
 - Shewhart charts, CUSUM charts or EWMA charts.

• Multivariate SPC tools (MSPC).

- ✓ Based on quality (Y) or on process variables (X).
 - Principal Component Analysis (PCA).
- ✓ Based on models relating process (X) and quality variables (Y).
 - Partial Least Squares regression (PLS).

Tools for process control

- **Setting the model of Normal Operating Conditions.**
 - ✓ Establishing process control limits (univariate tools).
Establishing boundaries of operational space (multivariate tools).
 - ✓ Limits or boundaries are set using historical data known to be under control.
- **Exploiting the model of Normal Operating Conditions.**
 - ✓ The model helps to predict whether observations from new processes are under or out of control.
 - ✓ Observations out of control are out of the control limits (univariate tools) or out of the space boundaries (multivariate tools).

Univariate SPC tools

- **Control charts.** Check the variability of a single quality attribute.
 - ✓ We need as many charts as quality attributes to control.
 - ✓ All of them work setting upper and lower control limits (UCL, LCL) that define normal variability.
 - ✓ Observations higher than UCL or lower than LCL are out of control.
 - ✓ The relationship among the different quality attributes monitored is ignored.

Univariate SPC tools


Types of control charts

- **Shewhart chart.** Looks at the values recorded during the process independently from each other.
 - ✓ Detects observations IN or OUT of control.
 - ✓ Detects clear non-random behaviour trends that can be sign of process malfunction.
- **CUSUM, EWMA charts.** Relate current and past observations recorded during the process.
 - ✓ Detects observations IN or OUT of control.
 - ✓ Detects slight non-random behaviour trends that can lead to OUT OF CONTROL situations.

Univariate SPC tools

Shewhart chart (1920)


- Plots observations of a process and compares them with a target value (often, a mean value). UCL and LCL are usually set as $\pm 3s$ with respect to the target value.



Observations above UCL or below LCL are out of control.

Univariate SPC tools

Shewhart chart




● Supplementary rules for control (*Western Electric, 1956*)

- ✓ 2 out of 3 consecutive points between UCL and UWL or LCL and LWL.
- ✓ 6 consecutive points systematically increasing or decreasing.
- ✓ 9 consecutive points above (or below) target point.
- ✓ Series of equal number of points alternating above or below target.

Univariate SPC tools

Shewhart chart



Detects **non-random trends** in observations.
Can be a sign of **process malfunction**.



Univariate SPC tools

CUSUM chart (Page, 1954) (CUMulative SUM control chart)

- Takes into account the present observation and all the previous ones into the parameter $CUSUM_t$.

$$CUSUM_t = \sum_{i=1}^t (x_i - \bar{x})$$

- Allows detecting slight shifts from the ideal behaviour in a process.





Univariate SPC tools

CUSUM chart (Page, 1954)

- Takes into account the present observation and all the previous ones into the parameter $CUSUM_t$.

$$CUSUM_t = \sum_{i=1}^t (x_i - \bar{x})$$



CUSUM charts detect more easily slight abnormal trends in process behaviour.

Univariate SPC tools

CUSUM chart (Page, 1954)

- Takes into account the present observation and all the previous ones into the parameter $CUSUM_t$.

$$CUSUM_t = \sum_{i=1}^t (x_i - \bar{x})$$

Parameters for CUSUM chart

- ✓ **Sensibility of the system (k).** Shift from the mean value to be noticed. E.g. shift to notice, $\delta=1 \Rightarrow 1\sigma$, $k = (\delta/2)\sigma$, $k=0,5\sigma$.
- ✓ **Control limit (h).** $h = 5\sigma$ (or 4σ are the most used).

Univariate SPC tools

CUSUM chart (current visualization)

- Plot of C_i^+ (positive deviations from the mean) and C_i^- (negative deviations from the mean) vs. Observation number.
- **Control limits:** set by h .

$$C_i^+ = \max \left\{ 0, C_{i-1}^+ + \underbrace{(\mathbf{x}_i - \bar{\mathbf{x}})}_{\text{Positive deviations } > k} - \mathbf{k} \right\}$$

Positive deviations $> k$

$$C_i^- = \max \left\{ 0, C_{i-1}^- - \underbrace{(\mathbf{x}_i - \bar{\mathbf{x}})}_{\text{Negative deviations } > k} - \mathbf{k} \right\}$$


Negative deviations $> k$

$$C_0^- = 0, \quad C_0^+ = 0$$

Univariate SPC tools

CUSUM chart (current visualization)


Classical CUSUM chart



Current CUSUM chart

$$k = 0,2$$

$$h = 1,6$$



Univariate SPC tools

EWMA chart (Roberts, 1959)

(Exponentially Weighted Moving Average control chart)

- Takes into account the present observation and the past ones. The weight of past observations (λ) decreases exponentially as they are further from the current observation.
- The plotted statistic (y_i) is defined as follows:

$$y_i = \underbrace{\lambda x_i}_{\substack{\text{Weight of} \\ \text{current} \\ \text{observation}}} + \underbrace{(1 - \lambda) y_{i-1}}_{\substack{\text{Weight of past} \\ \text{observations}}}$$

$$y_0 = \bar{x}$$

x_i current observation

λ weighting factor

$$1 < \lambda < 0$$

$\lambda \uparrow$ more importance to recent events

$\lambda \downarrow$ longer history of the process considered

Univariate SPC tools

EWMA chart (Roberts, 1959)

(Exponentially Weighted Moving Average control chart)

- The plotted statistic (y_i) is defined as follows:

$$\mathbf{y}_i = \lambda \mathbf{x}_i + (1 - \lambda) \mathbf{y}_{i-1}$$

- This is equivalent to:

$$\mathbf{y}_i = \lambda \mathbf{x}_i + \lambda(1 - \lambda) \mathbf{x}_{i-1} + \lambda(1 - \lambda)^2 \mathbf{x}_{i-2} + \lambda(1 - \lambda)^3 \mathbf{x}_{i-3} + \dots$$

Weights of further observations decrease exponentially!!

Usual λ values
 $0,25 > \lambda > 0,05$

Univariate SPC tools

EWMA chart (Roberts, 1959)

(Exponentially Weighted Moving Average control chart)

- Plots y_i vs. current observation number.

$$\mathbf{y}_i = \lambda \mathbf{x}_i + (1 - \lambda) \mathbf{y}_{i-1}$$

- **Limits of EWMA chart.**

✓ Change with the number of observations considered.

$$\mathbf{UCL}_i = \bar{\mathbf{x}} + L \sqrt{\mathbf{var}(y_i)} = \bar{\mathbf{x}} + L \sigma \sqrt{\frac{\lambda(1 - (1 - \lambda)^{2i})}{2 - \lambda}}$$

$$\mathbf{LCL}_i = \bar{\mathbf{x}} - L \sqrt{\mathbf{var}(y_i)} = \bar{\mathbf{x}} - L \sigma \sqrt{\frac{\lambda(1 - (1 - \lambda)^{2i})}{2 - \lambda}}$$

$L = 3$


Univariate SPC tools

EWMA chart (Roberts, 1959)


(Exponentially Weighted Moving Average control chart)

$$y_i = \lambda x_i + (1 - \lambda)y_{i-1}$$

Shewhart chart




EWMA chart



$$\lambda = 0,25$$

Limitations of univariate SPC charts


- One SPC chart is not sufficient to control a process.
- Univariate SPC charts ignore the relationship among variables to be controlled.



Multivariate Statistical Process Control (MSPC)


- Takes into account several variables at the same time.
- Considers correlation among variables.
- Can be carried out analysing one data table of process or quality variables.
 - ✓ **PCA-based process control.**
- Can be carried out relating a data table of process variables to another of quality variables.
 - ✓ **PLS-based process control.**

MSPC based on PCA



- Several variables characterize each process observation.
- All of them are analyzed simultaneously.
- For visualization, a low dimensional space (PC space) should be used.

MSPC based on PCA



- PCs do not repeat information among them.
- PCs preserve the information in original variables.
- PCs are linear combinations of original variables.

MSPC based on PCA





$$X = T P^T$$

Scores plot

(observation map in PC space)

Loadings plot

(variable map in PC space)



- PCA allows easier visualization of process observations (score plot) and process variables (loading plot).

MSPC based on PCA

Steps

- Building a PCA model from process data in NOC conditions.

$$\mathbf{X}_{\text{NOC}} = \mathbf{T}_{\text{NOC}} \mathbf{P}_{\text{NOC}}^{\text{T}} \text{Model}$$

- Project new process data using the model developed in NOC conditions.


$$\mathbf{T}_{\text{new}} = \mathbf{X}_{\text{new}} \mathbf{P}_{\text{NOC}}$$

- See whether the \mathbf{T}_{new} value is within the statistical boundaries of the score plot of NOC data.

MSPC based on PCA

Diagnostic tools based on PCA

- **Score plot.** Observations out of boundaries are OUT of control.




MSPC based on PCA

Diagnostic tools based on PCA

- **Score plot.** Observations out of boundaries are OUT of control.

- ✓ **Type 1.** Observations are OUT of boundaries but follow the tendency of the NOC model (**T² chart**).

- ✓ **Type 2.** Observations are OUT of boundaries and do not behave according to the model (**Q** or **SPE chart**).



(*) Adapted from B. Wise.

MSPC based on PCA

Diagnostic tools based on PCA

- **T² charts.** Based on the Hotelling's T² statistic. Compare the magnitude of the scores of a new observation with those from NOC observations.

$$T_{\text{obs}}^2 = \sum_{i=1}^{\text{PC}} \frac{t_{i,\text{obs}}^2}{s_{t_i}^2} = \sum_{i=1}^{\text{PC}} \frac{t_{i,\text{obs}}^2}{\lambda_i}$$

t_i Score value

s_{t_i} Variance of PC_{*i*}

λ_i Eigenvalue of PC_{*i*}

- **Q charts.** Show how big is the residual of the observation with respect to the projection in the PCA space.

$$\mathbf{T}_{\text{new}} = \mathbf{X}_{\text{new}} \mathbf{P}_{\text{NOC}} \quad \hat{\mathbf{X}}_{\text{new}} = \mathbf{T}_{\text{new}} \mathbf{P}_{\text{NOC}}^T$$

$$Q = \sum_{i=1}^{nv} (\hat{\mathbf{x}}_{\text{new},i} - \mathbf{x}_{\text{new},i})^2$$



MSPC based on PCA

Diagnostic tools based on PCA

• T^2 chart.

$$T_{\text{obs}}^2 = \sum_{i=1}^{\text{PC}} \frac{t_{i,\text{obs}}^2}{s_{t_i}^2} = \sum_{i=1}^{\text{PC}} \frac{t_{i,\text{obs}}^2}{\lambda_i}$$

Upper control limit $UCL(T^2) = \frac{A(m^2 - 1)}{m(m - A)} F(A, m - A), \alpha$

A nr. of PCs in the model
 m nr. of samples
 α confidence limit

• Q chart.

$$Q = \sum_{i=1}^{nv} (\hat{\mathbf{x}}_{\text{new},i} - \mathbf{x}_{\text{new},i})^2$$

Upper control limit

$$UCL(Q) = \theta_1 \left[\frac{h_0 p(\alpha) \sqrt{2\theta_2}}{\theta_1} + 1 + \frac{\theta_2 h_0 (h_0 - 1)}{\theta_1^2} \right]$$


$$\theta_k = \sum_{j=A+1}^{\text{PC}} (\lambda_j)^k$$

$$h_0 = 1 - \frac{2\theta_1 \theta_3}{3\theta_2^2}$$


MSPC based on PCA

Diagnostic tools based on PCA

T² chart



Q chart



- **Abnormal observations in T²:** they follow a normal process behaviour but are out of the domain identified as NOC. Maybe NOC conditions should be redefined.
- **Abnormal observations in Q or in Q and T²:** they show behaviour different from the process. The source(s) of abnormality should be identified.




MSPC based on PCA

Sources of abnormal process behaviour (contribution plots based on Q charts).

1. Identify abnormal observation (x_i)
2. Plot the residuals of observation x_i for each variable.

$$\mathbf{e}_i = \mathbf{x}_i - \hat{\mathbf{x}}_i$$

Contribution plot




High values in the
contribution plot




variables responsible for
abnormal behaviour.

MSPC based on PLS



MSPC based on PLS. The concept.



$$X = TP^T + E \quad \longrightarrow \quad U = TB_{PLS} \quad \longleftarrow \quad Y = UQ^T + E'$$

- X and Y are decomposed in PLS components.
- PLS components describe the covariance between X and Y .

MSPC based on PLS

Steps

- Building a PLS model from process data in NOC conditions.

$$X = T \boxed{P_{\text{NOC}}^T} \text{ Model} \quad Y = U \boxed{Q_{\text{NOC}}^T} \text{ Model} \quad U = T \boxed{B_{\text{PLS}}} \text{ Model}$$

- Project new process data using the model developed in NOC conditions.

$$T_{\text{new}} = X_{\text{new}} P_{\text{NOC}} \quad U_{\text{new}} = T_{\text{new}} B_{\text{PLS}} \quad Y_{\text{new}} = U_{\text{new}} Q_{\text{NOC}}^T$$

- See whether the Y_{new} and T_{new} values are within the statistical boundaries of the plots of NOC data.

MSPC based on PLS

- **T² chart** (on PLS scores of **X**)
- **Q chart** (on PLS scores of **X**)
- **Y predicted chart** (prediction of quality attributes).
 - ✓ Shewhart chart.


MSPC. Conclusions.

- Takes into account all process and/or quality variables in process control.
- Takes into account the natural correlation among variables.
- Allows process control in real time.
- Helps to check whether process and/or quality variables are IN or OUT of control.
- Helps to detect the end-point of a process (by comparing the observations of an evolving process with a model done with observations related to 'finished' processes).

Univariate SPC tools

CUSUM chart (classical visualization)

- Plot of $CUSUM_t$ vs. Observation number. $CUSUM_t = \sum_{i=1}^t (x_i - \bar{x})$
- **Control limits:** set by a V-mask built using k and h limits.
 - ✓ The V-mask was slid from last point and points out of it were out of control.



Points within the mask are in control.